

Invoice

To: The Chandlery Yacht Sales

Miles of view

From: John Pfarr
Po Box 551 Summerland, CA 93067

Date		Hours	Rate	Total
11/18/2011	John	2	\$50.00	\$100.00
	Inspect rigging			

Head sail halyard non operational
Head sail will not drop

Main sail wire halyard not lead properly to drum
Wire halyard hangs up behind drum

Main mast appears to be in fair to good condition
Main mast standing rigging appears to be in fair condition
Main mast running rigging appears to be in fair condition

Mizzen mast appears to be in fair to good condition
Mizzen mast standing rigging is in poor condition
Mizzen mast running rigging is in poor condition

Due to age and condition of rigging, re rigging
main and mizzen is recommended "Including furler"

Estimate for re rigging Including furler, crane and yard
Not including unforeseen hardware such as chain plates
or mast hardware \$12,000.00

Total hours	2	\$100.00
--------------------	----------	-----------------